



PCS-H100

PORTABLE HYDRAULIC PRESSURE CALIBRATOR

PCS-H100 is Portable pressure calibrator for Hydraulic pressure calibration up to 100 MPa with pressure generation and precise control. An independent pressure calibration system combining electrical signal measuring and loop power to quickly and easily calibrate for a large amount of on-site calibration.

Using lever type hand pump to generate up to 100 MPa and quickly and easily, and then use the built-in volume controller to precisely adjust the pressure with the secondary fine pressure control.

Full-graphic touchscreen display with intuitive menu selection makes it high visibility and operability.

Upper side of PCS-H100 can equipped quick connectors and adaptors for quick and easy to connect DUT.

- · Lever type hand pump to generate and control up to 100 MPa
- · 0.025% F.S Accuracy
- · Electrical connection for Transmitter
 - -Measure up to $\pm 15 \text{ V}$, $\pm 24 \text{ mA}$
 - -Source up to 24 VDC
 - -Loop Power
- · Pressure switch test, Help functions
- · Included carrying case
- · Available to apply pressure quick fittings (Optional)



Use

- · Potable pressure calibration
- \cdot Simple calibration for common calibration lab
- · Calibrate pressure gauge for pressure measuring instruments retail business
- · Pressure generating and controlling for pressure test lab
- · Pressure calibration for laboratory
- · Hydraulic high pressure calibration
- Easy & quick calibration for pressure transmitter, analog pressure gauge, digital pressure gauge, pressure switch test





02 Easy calibration task settings (Touch Screen)



Main Screen



Pressure/Electrical Measurement Screen



Help Screen Application connection diagram display function



Pressure Units Selection Available to select 13ea of pressure units

SOLUTION FOR PRESSURE **MEASUREMENT & CALIBRATION**



03 TASK menu (Advanced features)





PCS-H100

Pressure Max 0,000





Task Menu

Min/Max Test

.000

0.000

0.000

0.000

Start .11

Leak Test

Switch Test

04 **General Specifications**

Pressure range	0 to 100 MPa
Accuracy	± 0.025% F.S
Electronic measurement and source	±15 V.dc, ±24 mA.dc, Accuracy ± (0.01% of Reading + 1digit), Loop Power
Display	Full color touch screen LCD, 110 mm(4.3inch) diagonal. 480 x 272 pixels.
Power	Lithium-ion rechargeable battery, Charger 9V, 6A (5 hrs charge, 12 hrs battery life)
Workable Temperature Range	−20 to 70 °C (5 to 75 °C with water)
Storage Temperature Range	-30 to 80 °C (5 to 75 °C with water)
Temperature Compensated Range	−10 to 50 °C (5 to 75 °C with water)
Pressure units	Pa, hPa, kPa, MPa, bar, mbar, kg/cm², psi, mmH₂0, cmH₂0, inH₂0, mmHg, inHg
Test Port	1/4" PF Male
Weight	4.4 kg including batteries
Size	210 mm(W) × 360 mm(D) × 110 mm(H)
Oil Reserver Volume	100 cc
Media	Water or Mineral Oil

SOLUTION FOR PRESSURE MEASUREMENT & CALIBRATION



05 Ordering Information

PCS-H100 / Model (PCS-H100_Range) / Description (Portable Hydraulic Pressure Calibrator)

20 MPa 35 MPa 70 MPa 100 MPa 0 MPa to 20 MPa 0 MPa to 35 MPa 0 MPa to 70 MPa 0 MPa to 100 MPa

06 Accessories







Rechargeable battery



Battery charger



Test lead set

07 Optional items



Hydraulic Quick-connection adaptor set (up to 2,000bar) CA-H Series (1/4, 3/8, 1/2 PT | PF, NPT)

Flexible tubes (up to 630bar) FT Series (30 cm to 300 cm)



Traceable calibration report with data (KOLAS)

Pressure



CV KALINDRA MITRA NIAGA

Phone : 021-5541468 HP : 0816-110-5088

: suhadi@kalindramini.com : www.kalindramini.com www.kalindramitra.com

